## MEASURING STATION FOR BRACELET AND FOOTWEAR

Test station for simultaneous verification of correct grounding of the user's bracelet and footwear, according to **IEC 61340-5-1**. The footwear measuring is done independently between left and right foot at 50V or 100V for higher accuracy. Through an inner relay it is possible to access EPAs. Power supply: 9V battery or 9Vcc external power supply. ISO9000 certificate included.



Code	15064
Composition	Wristlab-II measuring station, Platform for measuring footwear and yellow support
Alternative code	9264.950



www.maxderbanchi.com



Wristlab-II measuring station



Platform



Complies to **IEC61340-5-1** regulations

